

Skiers observed collapsing on Weber Mountain near Lick Creek in Hyalite. They dug a pit and found poor structure with a thin, faceted snowpack and got poor stability test results, with ECTP6 failing on a thick layer of facets. Photo: M. Talty

Advisory Region
Northern Gallatin
Longitude
-110.96W

Latitude
45.53N

Forecast link: GNFAC Avalanche Forecast for Sat Jan 12, 2019
Northern Gallatin, 2019-01-11