

From obs 12/3/22: "Looking toward Ernie Miller ridge, we noted an old crown in the main bowl just below the summit. It was on an E-NE aspect, 200 or more feet wide and looked to be filled in with new snow but was still visible." Photo: H.Darby

Advisory Region
Southern Madison
Longitude
-111.10W

Latitude
44.96N
Avalanche Details: Two Natural Avalanches Ernie Miller
Southern Madison, 2022-12-04