

Natural avalanches were seen south of Cooke City, and many of the crowns have been filled in by recent wind. These likely happened last week during or near the end of the storm on 01/10. Photo: B. Fredlund

Advisory Region
Cooke City
Longitude
-109.94W
Latitude

44.99N
Avalanche Details: Republic Creek Avalanches
Cooke City, 2024-01-15