

Close up of a crystal from the surface hoar layer buried 2-3 feet deep north of Bridger Bowl and throughout most of the advisory area.

From 4/3/20: "I dug a quick pit at ~7450’ on a protected east 36 degree slope - HS 240cm...ECTP18@175 on 3-6mm preserved surface hoar (photos -1mm grid)... All results repeated identically in a second ECT... Seeing the reactive SH layer I opted out of skiing anything that had a distinct rollover or was steeper..." Photo: Z. Miller

Advisory Region

Bridger Range
Longitude
-110.93W
Latitude
45.84N

Forecast link: GNFAC Avalanche Forecast for Mon Apr 6, 2020
Bridger Range, 2020-04-05